




1/4






FIG. 3




FIG. 4







FIG. 2








Freehand region-of-interest measurement


FIG. 7





Poly-line curve measurement

FIG. 8



Poly-line curve measurement

FIG. 9